

N 8430B

Book # I

TRW HARTZELL PROPELLER
OWNER'S MANUAL AND LOG BOOK

N 8430B

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model HC-E3YR-1RF

Blade Design F 7673 DR

Diameter 78 INCH

Hub Ser. No. FTM 305

Blade Ser. Nos. _____

No. 1 E 96498 R

No. 2 E 96508 R

No. 3 E 96486 R

No. 4 _____

PITCH RANGE

High 35.0° Low 13.2°

Feather — Reverse —

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-14-87		PROPELLER S/N FTM 305 HAS BEEN OVERHAULED I/A/W HARTZELL MANUAL NO. 113-B. A.D. NOTE # 77-12-06, S.L.'S # 136-C, 143-A, 148-A, 152 AND S.B.'S # 118-C, 136-D & 142-B HAVE BEEN SATISFIED. DETAILS ON FILE UNDER W.O. # 17362.	
		JORDAN PROPELLER SERVICE, INC. CRS # 2273 Gary Jordan	
		THE MECHANIC MAKING THE INSTALLATION MUST <u>SEE</u> FAR #39.	
1-26-87	565.3	Installed propeller S/N FTM 305 on PA 32R-30T N 8430B.	
			Edward Meddell APP 452760326

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-22-91	937.	C/W AD 89-22-05 10/20/89 1AW Pan A# SB 165 found OK due again at TAC 987 END	James G. Adderbeck AP528/32615
1-27-92	1054.9	TT P-1054.9 - unwork prop fan overhaul - Trans of Dwyer 4P1940083	TT P-1054.9 - SMOH=489

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]