

NEW RECIPROCATING ENGINE CERTIFICATE

This is to certify that the engine as described hereinafter has been manufactured run-in and tested as prescribed by LYCOMING specifications and Federal Aviation Regulations. No further run-in is required. All applicable Federal Aviation Airworthiness Directives and Lycoming Service Bulletins have been complied with at time of Manufacture.

MODEL____TIO-540-AH1A SERIAL NO.

LYCONING

A Textron Company

THORIZED REPRESENTATIVE)

L-12470-61A

LYCOMING ENGINES

652 Oliver Street

Williamsport, PA 17701 U.S.A.

Form No. 777-B (Rev. 3/03)

OWNER

NAME	ADDRESS	Installed in Aircraft No.	Date
1		N213C	1 5 8 500c
2 —		3	
3 —			
4 —			
5			
6 —			

If this book is found, please return it to the owner.

NOTICE

Making false entries in this book is a violation of government regulations and is punishable by civil penalty.

THIS ENGINE SERVICED WITH

EXXON ELITE 20W50

OIL AT THE PIPER FACTORY

ENGINE DESCRIPTION

Manufacturer: Lycoming-Williamsport, Renn Serial No. 1-12470-61 Horsepower: 300 Model: TIO-540- AHIA FAA T. C. No. E14EA						
Engine Accessories	Serial No.	Weight				





Registration	N213C	Cutter Aviation San Antonio, Inc.	Hour Meter	35.8
Model No.	PA-32R-301T	367 Sandau Rd.	Total Time	35.8
Serial No.	3257436	San Antonio, Texas 78216	Landings	
		FAA Repair Station No. U7TR491Y		
		Phone 210) 384-3388 Fax 210) 384-3394		

Lycoming TIO-540-S1AD Total Time: 35.8 TSN: 35.8

- 1. 1. Drain oil, refilled with 12 qt. of Aeroshell 100 Plus in accordance with Piper PA-32-301T MM, Chap. 12-12-04.
- 2. Removed oil filter, and inspected, no discrepancies found., installed new Champion oil filter PN CH48110-1, in accordance with Piper PA-32-301T MM, Chap. 12-12-06.
- 3. Ground run engine and leak checked, no discrepancies found.

Maintenance was preformed in accordance with Piper PA-32R-301T Maintenance Manual, 761-879, dated March 19, 2005.

The aircraft/component identified above was maintained or altered in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed. All disrupted systems were restored and functionally tested in accordance with mfg's instructions. Pertinent details of the repair are on file at this repair station under Work Order: 11M-297

Date:

November 27, 2006

Authorized Signature:

Robert D. Bilbrey Jr.

ter	35.8
ne	35.8
;	

2-301T MM,

il filter PN

1-879, dated

rent regulations of med, All disrupted nent details of the

illey



Cutter Aviation Dallas, Inc. 5661 Mariner Dr. LB # 18 Dallas, TX 75237



Registration: N213C Model No. PA32R-301T Serial No. 3257436

Engine Log Entry

Hour Meter	45.5
Total Time	45.5

Changed oil and filter, serviced using Aeroshell 15W50 oil. Ground ran and checked for leaks.

The aircraft/component identified above was maintained or altered in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed. All disrupted systems were restored and functionally tested in accordance with mfg's instructions. Pertinent details of the repair are on file at this repair station under Work Order 1:06M-933

Date:	12-29-2006	CRS# UXCR663X	(1 And C	hristopher Gra	adisa
Date				•	

Date Engine Time		Time	Recorder	Maintenance		
Date	This Date	Since Major	Reading	Maintenance		
	Brought → Forward					
1-27-07	100 TACH			changed oil + filter		
<u> </u>				Changed out t fetter Ran and chuked for		
4-23-07	148.7			Charged oil + Filter replaced		
				Changed oil + Filter replaced Observed for leaker and revolved		
		·				
Total To Carry Forward						

¥						
laintenance	and Remar		Signature		Certificate No.	
fitter	ordeled Venko	12 QT	15 w 50 oil.	T-mis	karl	1A 2(2956/
replaced s and revolved.	CHU8110-1 a			HL Ca	ing	3126317 A+P
s and reconstend.	Leading the Business	S of Aviation	Cutter Aviation Dallas, Inc. 5661 Mariner Dr. LB # 18 Dallas, TX 75237		Pi	per
	Model No. PA	213C A32R-301T 257436	Engine Log Entry		Hour Meter	168.3
	Verified AD 2006-2	0-09 does not a 4-09 does not a	apply to serial number of engine. Apply to cylinders installed. Accounting bolts.			
	The aircraft/componen and is approved for ret	t identified above urn to service for	e was maintained or altered in accordance with curre the work performed. All disrupted systems were re air are on file at this repair station under Work Orde	stored and fund		
	Date: 6-8-200	7 CRS#	# UXCR663X	0	Chi	ristopher Gradisar

D-13	Engine Time		Recorder	Maintenance
Date	This Date	Since Major	Reading	Maintenance
	Brought Forward			
6-26-07 199.5 Hobbs Change oil w/ 10qts A and change oil filter w Degrease eng. Run u Ken Scheller A&P 18	W CH48110-1 no me Ip and leak check go 30442274	4-1 F 1		
15.6 2-22-07	ـــــــــــــــــــــــــــــــــــــ			Completed enspection 1 Au
ACH	226.0			completed inspection 1 Aq #5 7/3 #6 780. cleaned on and intake systems.
	***************************************	ware Land III		and intake systems.
certify that this	Engine			,
men neer Justicated	a accordance with		73000 VAN	
annual .nspection	and was deter			
The state of the s	C. michan			
Theodore C		(A)		
Total To Carry Forward	56.1			

aintenance	and Remarks	·	Signature	Certificate No.
				7,000
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
tion I Aw	pipe check list. Com	pression test &	设置 世口港	# 3港
ned and	pipe check list. Com	d mogreto terris	y. chakes	exhaust
Tims.	cherked AD Three 2007-		,	
		,	***************************************	

Date	Engine Time		Recorder	11 - 1 - 1 - 1 - 1		
Date	This Date	Since Major	Reading		Maintenance	
	Brought Forward					ne - Mandago y menenggang di James (Milita Mandago ang Angala Mandago y menenggang danakan dalah Sebanya sebanyang a
12-22-07	247.4			changed	oil + fu	tter
Leading the Business of Aviation		5661 N	Cutter Aviation Dallas, Inc. 5661 Mariner Dr. LB # 18 Dallas, TX 75237		Piper	
	Registration: N213C				Hour Meter	278.6
Model No. PA32R-301T		Engine Log Entry				
Serial No. 3	257436					
Fuel servo serial m	umber 70A46506 re	epaired by CRS# N	E2R028L. Adjus	ted idle speed and m	ixture.	
and is approved for re	eturn to service for the	e work performed. All	disrupted systems	with current regulations were restored and fund ork Order#: 06M-1457	of the Federal Aviation ctionally tested in accord	Administration dance with mfg's
Date: Februa	ary 13, 2008	CRS# UXCR6	63X	Ck-	Christo:	pher Gradisar
Total To Carry Forward						



r 278.6

Aviation Administration in accordance with mfg's

Ehristopher Gradisar

and Remarks			Signatu	Jre	Certificate No.
\ \ \ \					
added 10 Qt	auro Shell	154 50	Rete mich	and	1A2119561
				AANTO MA	
8-15-2008 3	08 Comp	leted inspen	etern , Au	s Rik	er check
<u>e</u>	diet.	cleaned and	reset.	spark	plup.
been inspected in accord	ence will I	exhaust an	4		
	coolins checker	magnete 2	iming . a	mpn	ession tes
Maios C. Mile D. D. P. 1129 BI (16	期 性 1 280 #	27% #3 73	世4%	#5 Z	影世6%
		405 Thm 200	1		
			1		
	a,	,			

Darka	Engine Time		Recorder	M-:		
Date	This Date	Since Major	Reading	Maintenance		
	Brought Forward			·		
3-06-09	334.9			cleaned and neset all		
*				spark plugs		
				fleofone a minhoud		
				1A 2(29561		
340-2009	3470			Completed inspection		
testily that this	Engne			spork plup. Changed		
Curry inspection	a ectordants with			Compresse test #1 750		
Theye	1 cmila	el.		Compresse test # 1 250		
A & P 212	Esichand, Tay					
Total To Carry Forward						

Maintenance	and Remarks	Signature	Certificate No.
reset all			
sud			
SALES CONTRACTOR OF THE SALES			
rection	Mr Liper check list, cleaned	and reset a	ll
Hanged	al + filter, added 11 Ots aero	Kell 15W 5	0.
l #1 750	oil + fitter, added 11 Ots acro- #27/30 # 3 180 #4 180 #5 780 #6 28.	clerked ofhans	and



Waco Regional Airport, Waco TX 76708

Reg. #: N213C Date: 10/18/2010 Make: Piper Model: PA-32R-301T Work Order #: 10-1001 Serial #: 3257436

Hour Meter: 380.4 ACTT: 380.4

Eng: TIO-540-AH1A S/N: L-12470-61A

тѕмон: 380.4

Performed annual inspection in accordance with FAR43 Appendix D and Piper Saratoga II TC maintenance manual. Compression check results as follows: #1 79/80, #2 78/80, #3 78/80, #4 78/80, #5 71/80, and #6 71/80. Drained oil and removed filter. Replaced oil with 12qts Aeroshell 15w-50 and filter with new P/N CH48110-1. Clean, gapped and rotated spark plugs. Performed idle mixture adjustment. Removed and replaced all leaking rocker cover gaskets P/N 67193. Washed engine. Run up checked O.K.

I certify that this engine has been inspected in accordance with a 100 hr/ANNUAL Inspection and has been determined to be in

Gary Drapela A&P 456337640 IA

Total To
Carry Forward



Waco Regional Airport, Waco TX 76708

Reg. #: N213C

Date: 11/23/2011 Work Order #: 11-1011 Model: PA-32R-301T

Serial #: 3257436

Make: Piper Hour Meter: 427.3

ACTT: 427.3

Eng: Lycoming TIO-540-AH1A S/N: L-12470-61A

TSN: 427.3

8/80, #5 and filter ustment. necked

ned to be in

Performed annual/100 hour inspection in accordance with FAR 43 appendix D and Piper maintenance manual. Drained oil and removed filter. Cut filter and inspected. Replaced filter with new P/N CH48110-1 and replaced oil with 12qts Aeroshell 15W50 oil. Compression tests as follows: #178/80, #2 76/80, #3 78/80, #4 75/80, #5 76/80 and #6 78/80. Cleaned, gapped, and inspected and rotated spark plugs. Checked magneto timing. Complied with A.D. 2008-14-07 inspection of fuel injector lines and line clamps. . Complied with A.D. 2009-02-03 per Precision Airmotive MSB PRS-107 Rev. 4 paragraph "G". Gasket P/N 2577258 installed and the letter "G" stamped on brass plug. Recurring requirements terminated. Re-secured cylinder head temp wiring. Tightened all rocker box drain tube coupling clamps.

I certify that this engine has been inspected in accordance with an ANNUAL Inspection and has been determined to be in an airworthy condition.

Gary Drapela A&P 3542901 IA



Waco Regional Airport, Waco TX 76708

Reg. #: N213C Make: Piper

Date: 12/18/2012 Work Order #: 12-1201 Model: PA-32R-301T

Serlal #: 3257436

Hour Meter: 477.2

ACTT: 477.2

Eng: Lycoming TIO-540-AH1A S/N: L-12470-61A

TSN: 477.2

Performed annual/100 hour inspection in accordance with FAR 43 appendix D and Piper maintenance manual, Drained oil and removed filter. Cut filter and inspected. Replaced filter with new P/N CH48110-1 and replaced oil with 12qts Aeroshell 15W50 oil. Compression tests as follows: #176/80, #2 74/80, #3 74/80, #4 78/80, #5 76/80 and #6 73/80. Cleaned, gapped, and inspected and rotated spark plugs, Installed new spark plug P/N RHB36S in #3 top position. Checked magneto timing. Cleaned fuel injectors. Installed new screw P/N STD-1925 in #3 rocker cover. C/W 400 hour rocker box inspection by inspection of rocker arms, valve tips, keepers, springs and spring seats. Complied with A.D. 2008-14-07 inspection of fuel injector lines and line clamps. Tightened all rocker box drain tube coupling clamps. Washed engine. Run up checked O.K.

I certify that this engine has been inspected in accordance with an ANNUAL Inspection and has been determined to be in an airworthy condition.

Gary Drapela A&P 3542901 IA

Total To Carry Forward



McGregor Executive Airport, Waco TX 76708

Reg. #: N213C

Date:2-14-14

Work Order #: 14-0207

Make: Piper Model:PA32R-301T Serial #: 3257436
Hour Meter: 607.9 ACTT:607.9 Eng: TSI0549AH1A S/N: L-12470

S/N: L-12470-61A TSMOH: 607.9

Performed annual/100 hour inspection in accordance with FAR 43 appendix D and Piper maintenance manual. Drained oil and removed filter. Cut filter and inspected. Replaced filter with new P/N CH48110-1 and replaced oil with 12qts Aeroshell 15W50 oil. Compression tests as follows: #176/80, #2 74/80, #3 74/80, #4 78/80, #5 76/80 and #6 73/80. Cleaned, gapped, and inspected and rotated spark plugs. Checked magneto timing. Cleaned fuel injectors. Complied with A.D.11-26-04 inspection of fuel injector lines and line clamps. Washed engine. Run up and leak checked O.K.

I certify that this engine has been inspected in accordance with an <u>ANNUAL / 100 Hr</u> Inspection and has been determined to be in all airworthy condition.

Carl Farris A&P 3225044 I.A.

Approving National Aviation 2
Authority/Country:
FAA/UNITED STATES **AUTHORIZED RELEASE CERTIFICATE** 4089794 FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG Cessna Aircraft (ompany (PC4) PN: CH48110 Cessna Parts Distribution Dept. 702 5800 E Pawnee, Wichita, KS 67218 1337444 Parl Humber 9. Eligibaty. 12 Status/Work FILTER OIL CH48110-1 N/A N/A AIRWORTHINESS APPROVAL - PARTS. THIS FORM IS NOT AN EXPORT APPROVAL. PO# AA14-03156 Approved distily date and are at a condition for a Howepreved design date specified in Block 13 15 Authorized Signature Marlyn H. Farber ODA 00129-CE 17. Name (Typed or Printed) 18. Date (m/d/y): MARILYN K. FARBER JAN/13/2014 important to understand that the existence of this document alone does not automatically constitute authority to install the part/componentiasses on the user/installer performs work in accordance with the relational regulations of an abvordances authority different than the airworthness authority different than the airworthness authority is a second that the user/installer ensures that higher airworthness authority accepts parta/components/assembles from the party of the country specified in Block 1. people in Block 1, it is essential that the user/astaller ensures that higher alworkiness automatic and advantage * Installer must cross-check eligibility with applicable technical data NSN: 0052-00-012-9005

: #176/80, #2 ated spark Cleaned fuel ox inspection A.D. 2008-14coupling

naintenance

2/N

ined to be in an



McGregor Executive Airport, McGregor TX 76657

Reg. #:N213C

Date: 4-03-15

Work Order #: 15-0060

Make: Piper

Model: PA-32R-301T

Serial #: 3257436

Hobbs: 651.0 **TSMOH:** 651.0

Eng: Lycoming TIO-540-AH1A **S/N:** L-12470-61A Performed an Annual Inspection as required by FAR 91.409 in accordance with the Cessna service manual, and FAR 43 Appendix D. Accomplished the following items:

- Compressions check results: 1)74/80, 2) 74/80, 3) 74/80, 4) 73/80, 5) 75/80, 6) 74/80.
- 2) Drained oil and serviced engine with 12 quarts of Phillips 15W50. Replaced oil filter with new CH48110-1. Cut open old filter and inspected for metal, none detected at this time. Leak check satisfactory.
- 3) Replaced broken exhaust support cable P/N LW19189 and nut P/N STD-1411 with new.
- 4) Adjusted idle RPM and mixture, found servo not operating normally, removed fuel servo P/N 2576554-3 S/N 70A46506 and sent for overhaul. Received exchange fuel servo P/N 2576554-3 S/N 72FT8102 and installed onto engine using tow new washers P/NSTD1727. Performed ground run up and leak check. Set engine idle RPM and mixture. Ops check good and no leaks noted at this time.

I certify that this engine has been inspected in accordance with an ANNUAL / 100 Hr Inspection and has been determined to be in an airworthy condition.

Carl Farris A&P 3225044 LA.

Carry Forward

:: 651.0 I: 651.0 2 Cessna

1/80. oil filter d at this

h new. :I servo P/N N 2576554-3 rformed ground leaks noted at

ned to be in



McGregor Executive Airport, McGregor TX 76657

Reg. #:N213C Make: Piper

Date: 05/30/2016 Model: PA-32R-301T

Work Order #: 16-0224 Serial #: 3257436

Hobbs: 651.0

Eng: Lycoming TIO-540-AH1A S/N: L-12470-61A **TSMOH:** 687.5 Performed an Annual Inspection as required by FAR 91.409 in accordance with the Cessna

service manual, and FAR 43 Appendix D. Accomplished the following items:

- Compressions check results: 1)73/80, 2) 72/80, 3) 73/80, 4) 72/80, 5) 72/80, 6) 71/80.
- Drained oil and serviced engine with 12 quarts of Aeroshell 15W50. Replaced oil filter with new CH48110-1. Cut open old filter and inspected for metal, none detected at this time. Leak check satisfactory.
- Removed, cleaned, gapped, and rotated plugs. P/N RHB36S. Found 3 plugs with cracked insulators replaced with P/N RHB36S. Installed all spark plugs with new gaskets P/N M674.

Lectify that this engine has been inspected in accordance with an ANDEDAL / 100 Hr Inspection and has been determined to be in

rfis A&P 3225044 I.A.



McGregor Executive Airport, McGregor TX 76657

Work Order: 17-0295

ENG Mdl:	ENG SN:	Position:		Hobbs:	Date:	
Lycoming TIO-	L-12470-	Main		706.7	08/09/17	
540-AH1A	61A					

Performed an Annual Inspection as required by Far 91.409 in accordance with Piper PA-32R-301T maintenance manual and FAR 43 Appendix D. Accomplished the following items:

- 1) Compression Test results: #1) 74/80, #2) 78/80, #3) 74/80, #4) 77/80, #5 76/80, #6 78/80.
- 2) Changed oil with 12qts new oil Aeroshell 15W50.
- 3) Removed and replaced oil filter with new filter P/N CH48110-1. Cut open old filter to check for containments no defects noted.
- 4) Cleaned and gapped spark plugs.

I certify that this **engine** has been inspected in accordance with an **ANNUAL** Inspection and has been determined to be in an airworthy condition.

Gary Drapela A&P 3542901 i.A.



McGregor Executive Airport, McGregor TX 76657

Work Order: 18-0562 N213C

, TOTAL OTTO TO THE THE TENT						
ENG Mdl:	ENG SN:	Position:	TSMOH:	Hobbs:	Date:	
Lycoming TIO-	L-12470-	Main	748.1	748.1	12/28/18	
540-AH1A	61A					

Performed an Annual Inspection as required by Far 91.409 in accordance with Piper PA-32R-301T maintenance manual and FAR 43 Appendix D. Accomplished the following items:

- 1) Compression Test results: #1) 74/80, #2) 77/80, #3) 78/80, #4) 78/80, #5 76/80, #6 76/80.
- 2) Changed oil with 12qts new oil Aeroshell 15W50.
- 3) Removed and replaced oil filter with new filter P/N AA481110-2. Cut open old filter to check for containments no defects noted.
- 4) Cleaned and gapped spark plugs.
- 5) Replaced the top #4 spark plug due to ceramic being chipped.
- 6) Replaced oil quick drain plug and installed a new quick drain plug P/N CCB-37000 IAW Lycoming TIO-540-AH1A MM.

A.D. 2015-19-07: Inspected fuel injection lines and clamps IAW MSB 342G. No defects noted at this time

I certify that this **engine** has been inspected in accordance with an **ANNUAL/100Hour** Inspection and has been determined to be in an airworthy condition.

Gary Drapela A&P 3542901 I.A.

Date: '09/17

Piper he

/80,

old

ermined to be in an