

# *Executive Propellers* *inc.*

16140 COVELLO STREET • VAN NUYS, CALIFORNIA 91406

**(818) 779-7767 • FAX (818) 779-0848**

*FAA CRS # EU6R595N*



## PROPELLER LOGBOOK



*Thank You for choosing Executive Propellers, Inc.*

## **WARRANTY**

All propellers overhauled by Executive Propellers, Inc. will carry what we believe to be the most comprehensive warranty in the industry.

Executive Propellers, Inc. offers a Full TBO Warranty. This warranty will cover workmanship and parts that were replaced at the time of overhaul.

This warranty entitles purchaser to repairs through Executive Propellers, Inc. only. Assemblies must be accompanied by original Invoice/Work Order or Logbook.

# PROPELLER MAINTENANCE RECORD

Propeller Manufacturer:

McCawley

Hub Model No.

3AF32C508

Hub Serial No.

902449

Blade Model No.

82 NFA-6

Blade Serial No. 1

KH 306

No. 2

KH 310

No. 3

KH 319

No. 4

h h h

No. 5

## PITCH RANGE

High

14.6°

Low

11.0°

Feather

82.3°

Reverse

2

Governor Manufacturer:

Governor Model No.

Governor Serial No.

Maximum Hours or Service Life between overhaul recommended by Mfg.

2000

Hrs. or

Six

years, whichever occurs first.

## CUSTODY RECORD

Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____
Owner _____	Date Rec'd. _____

Make/Model

Serial #


Aircraft Installed On: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

## OVERHAUL RECORD

No.	Date	Repair Station and No.	Signature
	6-11-2003	Executive Propellers, Inc. 16140 Covello St., Van Nuys, CA FAA CRS # EU6R595N	

Country: 1.

2.

3. Form Tracking Number:

03-218

UNITED STATES

## AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

## 4. Organization Name and Address:

EXECUTIVE PROPELLER  
16140 COVELLO STREET  
VAN NUYS, CAL. 91406

## 5. Work Order/Contract/Invoice Number:

W.O. 03-218

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	MCCADLEY PROPELLER	JAF32C508/82NFA-6	PIPER SENECA III	1	ASSY S/N 902449 BLADE S/N'S KH306 KH310 KH319	OVERHAULED

## 13. Remarks:

PROPELLER OVERHAULED I.A.W. MFSG. MANUALS 810915, BOM100-1, SPM100-1. FUNCTIONALLY BENCH TESTED AND ANGLES SET TO MFSG. SPECS. @ 11.0 LOW PITCH : 14.6 LATCH : 82.3 FEATHER.  
S/B'S ALL REVIEWED & COMPLIED WITH @ 119A, 143, 145, 147.  
S/L'S ALL REVIEWED & COMPLIED WITH @ 85-6, 87-3, 98-23, 00-2, 00-19, 01-14, 02-6, 02-17.  
A.D. 83-13-06 IN COMPLIANCE @ LATEST STYLE COUNTERWEIGHT BOLT INSTALLED  
\*A1635-125\* I.A.W. MFSG. S/B 147.

## 14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.  
☐ Non-approved design data specified in Block 13.

19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

## 15. Authorized Signature:

## 16. Approval/Authorization No.:

## 20. Authorized Signature

## 21. Approval/Certificate No.:

EU6R595N

## 17. Name (Typed or printed):

## 18. Date (m/d/y):

## 22. Name (Typed or Printed):

JUAN SALAS

## 23. Date (m/d/y):

05/11/2003

## User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

Tom's Aircraft Phone 1-562-426-5331

Maintenance Inc FAX 1-562-426 1052

2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

N134MG Hobbs: 1621.3 SO# 03-12856 6/23/03

**LH Propeller:**

This propeller was removed and overhauled. Reinstalled per the Piper Service manual. This propeller has been inspected in accordance with a 100hr./Annual inspection and has been found to be in an airworthy condition and is approved for return to service.

*Tom L. Jacobson*  
TOM L. JACOBSON FAA REPAIR STATION VTMR569K

DESCRIPTION

Tom's Aircraft Phone 1-562-426-5331  
Maintenance Inc Fax 1-562-426-1052

2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

RH PROPELLER

N134MG DATE 7/9/2004 HOBBS 1644.8 SO# 04-13550

This propeller was inspected in accordance with a 100hr / annual inspection. This inspection used the Piper service manual as a reference. Ran the engine. Opps checked well. This propeller is approved for return to service.

FRANCIS SALISBURY FAA REPAIR STATION VTMR569K

Tom's Aircraft  
Maintenance Inc

Phone 1-562-426-5331  
FAX 1-562-426 1052

2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

N134MG

LH PROPELLER

TSMOH 23.5

HOBBS 1644.8

TOTAL TIME 1644.8

I CERTIFY THAT THIS PROPELLER HAS BEEN  
INSPECTED IN ACCORDANCE WITH A 100HR/ANNUAL  
INSPECTION AND WAS FOUND TO BE IN AN  
AIRWORTHY CONDITION. ALL DETAILS OF THIS  
INSPECTION ARE ON FILE AT THIS FACILITY UNDER  
WORK ORDER# 04-13550 DATED 7/9/2004

AUTHORIZED SIGNATURE \_\_\_\_\_  
FAA REPAIR STATION# VTMR569K

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR AIRCRAFT

Tom's Aircraft Phone 1-562-426-5331  
Maintenance Inc FAX 1-562-426-1052


2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

N134MG Hobbs: 1662.6 TSMOH: 41.3 T.T.: 663.6

SO# 05S-14369 10/20/05

LH Propeller:

I certify that this propeller has been inspected in accordance with a  
100 hr/Annual inspection and was found to be in an airworthy  
condition. All details of this inspection are on file at this facility  
under work order #05S-14369 dated 10/20/05.

  
TOM L. JACOBSON FAA REPAIR STATION VTMR569K

Tom's Aircraft  
Maintenance Inc

Phone 1-562-426-5331

Fax 1-562-426-1052

2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

LH PROPELLER

N134MG DATE 11/3/2006 HOBBS 1671.6 SO# 06-15246

This propeller was inspected in accordance with a 100hr / annual inspection. This inspection used the Piper service manual as a reference. Ran the engine. Opps checked well. This propeller is approved for return to service.

FRANCIS SALISBURY FAA REPAIR STATION VTMR569K

Tom's Aircraft  
Maintenance Inc

Phone 1-562-426-5331

FAX 1-562-426 1052

2641 E Spring Street \* Long Beach Int'l Airport \* Long Beach, CA 90806

N134MG

LH PROPELLER

TSMOH 50.3

HOBBS 1671.6

TOTAL TIME 671.9

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100HR/ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ALL DETAILS OF THIS INSPECTION ARE ON FILE AT THIS FACILITY UNDER WORK ORDER# 06-15246 DATED 11/3/2006


AUTHORIZED SIGNATURE \_\_\_\_\_

FAA REPAIR STATION# VTMR569K


DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS



DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		<b>N134MG Left Propeller, McCauley 3AF32C508 S/N 902449</b> <b>Date: 01/26/2008, Hobbs: 1793.8, Engine Total Time: 1793.8, TSOH: 172.50</b> Dressed propeller. . All applicable AD's complied with to date, See AD list in aircraft logs. I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.	Signed  John E. Davolt 2036047 IA

**N134MG Left Propeller, McCauley 3AF32C508 S/N 902449**  
**Date: 03/08/2009, Hobbs: 1848.3 Propeller Total Time: 1848.3, TSOH: 227.0**  
Dressed propeller. . All applicable AD's complied with to date, See AD list in aircraft logs. I  
certify that this Propeller has been inspected in accordance with an Annual Inspection and was  
determined to be in airworthy condition.

Signed   
John E. Davolt 2036047 IA

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS


DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
------	-----------	---------------------	-----------

**N134MG Left Propeller: McCauley 3AF32C508 S/N: 902449**

**Date: 3/30/2010, Hobbs: 1866.5, Propeller Total Time: 1866.5, TSOH: 245.2**

Dressed Propeller. All known AD's complied with to date, a summary of applicable AD's and their compliance accompany the log books. I certify that this Propeller has been inspected in accordance with a 100 Hrly Inspection and was determined to be in airworthy condition.

Signed: \_\_\_\_\_

  
John E. Davolt AP 2036047 IA


**JD's Professional Aviation Services**  
163 24000 Rd, Cherryvale, Ks 67335

**N134MG Left Propeller: McCauley 3AF32C508 S/N: 902449**

**Date: 04/10/2011, Hobbs: 1907.1, Propeller Total Time: 1907.1, TSOH: 285.6**

Dressed Propeller. All known AD's complied with to date, a summary of applicable AD's and their compliance accompany the log books. I certify that this Propeller has been inspected in accordance with a 100 Hrly Inspection and was determined to be in airworthy condition.

Signed: \_\_\_\_\_

  
John E. Davolt AP 2036047

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS


JD's Professional Aviation Service  
163 24000 Rd, Cherryvale, KS 67335

**N123MG Left Propeller: McCauley 3AF32C508, S/N: 902449**

**Date: 05/11/2012, Tach: 1952.3 Propeller Total Time: 1952.3, TSOH: 330.8**

Dressed Propeller. All known AD's complied with to date, a summary of applicable AD's and their compliance accompany the log books. I certify that this aircraft has been inspected in accordance with a 100 Hrly Inspection and was determined to be in airworthy condition.

Signature:

  
John E. Davolt, 20360471A

JD's Professional Aviation Service


163 24000 Rd, Cherryvale, KS 67335

**N123MG Left Propeller: McCauley 3AF32C508, S/N: 902449**

**Date: 05/03/2013, Tach: 1991.4 Propeller Total Time: 1991.4, TSOH: 369.9**

Dressed Propeller. All known AD's complied with to date, a summary of applicable AD's and their compliance accompany the log books. I certify that this aircraft has been inspected in accordance with a 100 Hrly Inspection and was determined to be in airworthy condition.

Signature:

  
John E. Davolt, 20360471A

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS



Pueblo Memorial Airport  
522 Skyway St Pueblo CO 81001

N134MG -- LEFT PROP      DATE: 4 JUN 2014      PROP TT: 2024.3      TSMO: 402.8  
PERFORMED A 100 HR / ANNUAL INSPECTION IN ACCORDANCE WITH FAR 43 APPENDIX D. I CERTIFY THAT THIS  
PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR / ANNUAL INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION. John E. Davolt *John E. Davolt* A&P20360471A



Pueblo Memorial Airport  
522 Skyway St Pueblo CO 81001

N134MG -- LEFT PROP      DATE: 17 JULY 2015      PROP TT: 2070.7      TSMO: 449.2  
PERFORMED A 100 HR / ANNUAL INSPECTION IN ACCORDANCE WITH FAR 43 APPENDIX D. I CERTIFY THAT THIS  
PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR / ANNUAL INSPECTION AND WAS DETERMINED  
TO BE IN AN AIRWORTHY CONDITION. John E. Davolt *John E. Davolt* A&P20360471A

BEVAN-RABELL, INC. 1880 S AIRPORT ROAD WICHITA, KS 67209 CRS KG2R951K  
LOG ID# 7848 20-September-2016 WO# 62339 AC TT 2086.5 HOBBS 2086.5  
N134MG S/N 34-8233007 PIPER PA34-220T

Pg 1 / 1

PERFORMED ANNUAL INSPECTION IAW FAR 43 APPENDIX (D) USING PIPER SENECA INSPECTION FORM AS A GUIDE.  
DRESSED PROP BLADES. ALL APPLICABLE AD'S CHECKED THROUGH THIS DATE.  
I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND  
WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE MAINTENANCE PERFORMED  
ARE ON FILE AT THIS REPAIR STATION UNDER W/O 62339.

KG2R951K RUSSELL PARKER

Date

*Russell Parker* 9-20-2016

BEVAN-RABELL, INC. 1880 S AIRPORT ROAD WICHITA, KS 67209 CRS KG2R951K  
LOG ID# 8711 08-February-2018 WO# 66083 AC TT 2100.0 HOBBS 2100.0  
N134MG S/N 34-8233007 PIPER PA34-220T

Pg 1 / 1

PERFORMED ANNUAL INSPECTION IAW FAR 43 APPENDIX (D) USING PIPER SENECA INSPECTION FORM AS A GUIDE.  
ALL APPLICABLE AD'S CHECKED THROUGH THIS DATE.  
I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND  
WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE MAINTENANCE PERFORMED  
ARE ON FILE AT THIS REPAIR STATION UNDER W/O 66083.

KG2R951K RUSSELL PARKER

Date

*Russell Parker* 2-8-2018

# FAA AIRWORTHINESS DIRECTIVES COMPLIANCE RECORD

Year: <u>2003</u>	Total Hours	<p>Complied by the following:</p> <p><i>Installed new Counterweight bolts P/N A1635-125 at this overhaul - 6/11/2003. NO further action required</i></p> <p style="text-align: right;"><i>Executive Propellers, Inc.</i> 16140 Covello St., Van Nuys, CA FAA CRS # EU68895N</p>
Date: <u>6/11</u>		
A.D. #  <u>83-13-06</u>		
Next Inspection Due:  <i>at overhaul</i>		
		Signature: <i>[Signature]</i>

Year: _____	Total Hours	<p>Complied by the following:</p>
Date: _____		
A.D. # _____		
Next Inspection Due: _____		
		Signature: _____