FIRST PAGE OF FRENCH LOGBOOKS

S.E.R.A.L

COMPTE-RENDU DE TRAVAIL

ASRODROME DES MILLES 19290 LES MILLES TEL: 42.60.00.37 AGREMENT U 121

C.R.I. IMMATRICULATION AVION DATE

0479 F.GHSO 20/03/91

FICHES TRAVAUX 0479

DATE CDN: DATE CER:

DATE BALISE RDBA: 01/06/91

TYPE VISITE: COMPLEMENT VISITE 2000 HEURES 4 ANS

REFERENCE PROGRAMME SERAL

	MARQUE	TYPE	NUM .SERIE	HEURES T.	HEURES R.
CELLULE	PIPER	PA32-301T	32-8224006	1.022h	h
MOTEUR G	LYCOMING	T10-540-S1AD	L.8100-61A	1.022h	h
MOTEUR D				h	h
HELICE G	HARTTZELL	HC E3YR-1 R F	F M 348	1.022h	h
HELICE D				h	h

DATE HELICE G: 16/01/87 DATE HELICE D:

COMPRESSIONS MOTEUR G sur 80 PSI: 1: 76 2: 76 3: 74 4: 70 5: 78 6: 76 2: 5: COMPRESSIONS MOTEUR D sur 80 PSI: 1: 3: 1:

TYPE HUILE : AERO DM TYPE FILTRE A HUILE: CH 48110

MISE à JOUR TECHNIQUE - MODIFICATIONS

CN 90 - 229 filtre à air conforme

CN 89 - 129 appliquée aux USA par AD 89-12-04

CN 78 - 22 appliquée aux USA avec visite # vnip le 1.16.87 CN 83 - 033 magnéto BENDIX due à 1.099,00 H

CN 81 - 080 classification vérifiée

CN 86 - 049 pompe à vide NC

III TRAVAUX SUPPLEMENTAIRES

Désactivation STC n. SA 2586 NM (EGT-CHT monitor)

Dépose réservoir supplémentaire

Pesée

Désactivation STC n. SA 689 GL (aux.pump.)

Ili PIECES CHANGEES

Pièces exigées par protocole

TRAVAUX DIFFERES

Hydrotest oxygène au 01.02.1994

Demande d'approbation des 2 STC désactivés

VI VCL DE CONTROLE EFFECTUE le

19-04-91

APPROBATION POUR REMISE EN SERVICE SIGNATURE du RESPONSABLE TECHNIQUE:



AIRCRAFT RECORD

Durée du vol Duration of flight	Heures totales Hours since manufacture	Heures depuis entretien majeur Hours since major maintenance	Nombre d'atterris- sages Number of Landings
माम्स्य 🔭 🖂		17 1	y" 2"
10.01 - 2.1			
	V	1016-1-1	4
		141 - 12	S.
	A.3 3M	20	
1.9	6202160 1,82 200	i horak is	,
z	The State of the state of	CIE 74 5-UT- 1976	
	15. · · · · · · · · · · · · · · · · · · ·	hours?	
, î., î.	" S(00), sett 7""		
1	/1	1 1/1/2	
	м.		

LAST PAGE

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

L		
Dates	Détails vérifications et travaux entretiens — Révisions partielles ou générales Modifications — Essais en vol	Cachet — Signature réparateur Organisme de contrôle
Date	Particulars of inspections and maintenance — Minor or major overhauls Modifications — Test flights	Stamp and signature of overhauler and of controlling Authority
7/11/9	Cherterel Airport Hanger 3 8 0 - 6041 GOSSELIES I certified that this	GEMS S.A.
	Charlerol Airport Hangar 8 8 8 - 6041 COSSELIES I certified that this	JAR-145 AUTHORIZED STATION
	inspection and was determined to be in	APPROVAL NUMBER BEL-36
	Signed Date	808)
	Tot. Time: 14/3:18 ppt / Hobbs: delector	400
	A. A	T. ERNST
	Verification AD97-16-10 Kales-Liller	QUALITY CONTROL.
	Vérification AD97-16-10 Rajes-filter	JAK-145 - REF W BEL-30
	REPLACE ELT BATTERY BY:	
	1 5 -10- 1999	
		•



	MAFT LOG				
This Date Total	Recorder Reading	Maintenants and Remarks	Registration No.	Signature	Certificate
Transponder tests required by FAR 91.413 were performed this date and found to comply with FAR part 43	Data correspondence tests require 91.217 were performed this date to comply with FAR part 43 ap	red by FA. and found ppendix E	P. Cors DG Som TO 105TA Claras OU CAU-Air 62-014-4 S/DA 76HEARFRAME, EN ANCE WAS REPA ANCE WAS REPA ANCE WAS REPA	upo A3816	
MAKECALLI MODEL DATES OF IS 78 3 Details on file under W.O. 43846 Sign Date 12-38	para. "C". Next certification due.	-2-98	RETURN TO SERV	IN A STREET OF THE REPAIR ARE ON THE REPAIR ARE	-
THE ALTIMETER AND STATIC SYSTEM HAVE BEEN TESTED IN ACCORDANCE WITH THE REQUIREMENTS TO SEE ALTISFACTORY.			Signed FAA Repair S CAV-AIR.	tel PSLR 82TD NC. Executive Airport	
FOR CAV-AIR, INC. CAV-AIR, INC. FOR CAV-AIR, INC. Total To					·
Carry Forward					

D-1	Date Aircraft Time		Recorder	Maintenance
g Date	This Date	Total	Reading	Maintenaries
MFG/MOI I certify the level flight with fuel to Scale read LH MAIN Scales Mo		A 32-301T as weighed i closed hanga 11 IAIN 1138 AIRFRA	SERIAL 32: n accordance war. Weighed with O NOSE/TAIL Calibrated 9/	744.0

N-255DS PA-32-301T S/N 32-8224006 HACTT 2393.0 TACH 2393.0 1/27/98

AIRFRAME

C/W ANNUAL INSPECTION USING PIPER FORM. REPLACED ATTACH HARDWARE IN LOWER VERTICAL FIN COVER. INSTALLED NEW O.A.T GAUCE. RE-SKIN RUDDER USING FACTORY PIPER SKIN. P/N 63396-02. SERVICED ALL LANDING GEAR STRUIS PER PIPER MAINT MANUAL. PREFORMED HYDROSTATIC TEST ON O' BOTTLE, RE INSTALLED AND SERVICED. REPLACED NOSE TIRE AND SERVICED PER SPECS . C/W AD 96-10-03 BY INSPECTION FOUND TO BE P/C/W . C/W -AD 76-07-12 BENDIX IGN. SWITCH FUNCTION CHECK, DUE AGIAN IN 100 HRS. REPLACED LEFT HAND LOWER COWL LOUVER, REPAIRED RIGHT HAND. REPLACED CENTRAL VAC FILTER. REPLACED AFT ENTRANCE DOOR SEAL. REPLACED CABIN ENTRANCE DOOR LOCK ASSEMBLY. INSTALLED NEW TURN COORDINATOR MODEL # 1394T100-72 S/N 9709-360. REPLACED CABIN HEAT CONTROL CABRE. OPS CHECK O.K.. REPAIR VERTICAL FIN BASE COVER ASSEMBLY.

I certify that this Aucroff inspected in accordance with a Aurust inspection and was determined to be in Airworthy condition./ 27-2398.0

CAV-AIR INC.

FAA Approved Repair Station FBL R#21D

	3. System Tracking Rel. No
1. United States 2. FAA FORM 8130	Lo. Sustam Tracking Rel. No.
Amagina EORM 81:30	3
SERVINIC SERVINIC	S SERVICES, INC. 3309 (954) 491-3170/776-6550
TOWARD CIAL BLVD. FILOW WAS RE	PAIRED AND INSPECTED TRAINING AND IS PAIRED AND INSPECTED THE REPAIR ARE ON THE REPAIR ARE ON
4. Organization 1575 W. COMMUNICE IDENTIFIED BELOW THE APPLIANCE IDENTIFIED BELOW THE FE THE APPLIANCE IDENTIFIED BELOW TO SERVICE. PE	PETALS OF THE HAND OF THE PETALS OF THE PETA
THE APPLIANCE REGULATIONS ERVICE. PE WITH CURRENT REGULATIONS ERVICE. PE APPROVED FOR RETURN TO SERVICE. PE APPROVED FOR	174E NO. 1
Herry 1073	
PI CON	10
WOOD CIAU ATT	autu
Details on Rie CUST 78 98 TECH 1 TECH DATE DATE PARAMO	ALIDERDALE EXECUTIVE AIRPORT
Limited Life pu Limited Life pu 14. Ne Corridoe that to opening in a ACTION TAKEN ACTION TAKEN ACTION TAKEN LOCATED AT BANYAN AIR SERVICE LOCATED AT BANYAN AIR SERVICE	FT. LAUDERDALE EXECUTIVE AIRPORT SD4RS14M 23. Delse: - 28 - 98
MOTE is case of 15. Signature: 18. Date:	Tro synds or Printing
17. Name (typedam Printed):	ned Installor must check eligibility with applicable technical class.
2000	
Ft. Lauderdale, Florida	
	tied .
Total To Carry Forward	

Registration No.		
and Remarks	€ Signature	Certificate No
Aircraft Registration: N255DS Serial Number: Aircraft Model: Saratoga Date: Feb. 24.98 W.O. #: 1 This is to certify that this aircraft was striped down of Corrosion protection applied. Aircraft was primed with verpainted. Flight controls balanced and re-installed on the a Carried out complete operational check on all flight controls with factory instructions for this make and model. Colors used for this aircraft: Base Color: JetGlow Matternal Accent — I: G5003 Aristol Blue Accent 100% one-year warranty limited to paint and material only of Signed by Inspector:	Make: Piper 100 old paint. Removed convash primer and high busincraft. Installed decal kit. ols. All work preformed orn White (#1528) -II: HT 10494 Las Vegas cover this work.	ntrol surfaces. ild primer and in accordance
A&P591-44-82	43	

AERO DESIGN, INC.

Aircraft Painting, Interiors, and Woodwork. Fort Lauderdale Executive Airport (KFXE) 5601 N.W. 15th Ave., Fort Lauderdale, FL 33309. Phone: (954) 938-2188. Fax: (954) 771-4583.

0-4-	Aircraft Time		Recorder	Malatanana
Date	This Date	Total	Reading	Maintenance
	Brought Forward →			
28-98	Ronov	o A/P (onlito	10757 S/2.1/748
e:/c	771-81	v 956.	For Su	slot Rosa
a	Lastall	A/P Com	convis	Rose Carries ou
	THE AIRF	AME, ENGINE OR	COMPONENT	ACCORD-
3	ANCE WIT	H CURRENT REG ADMINISTRATION O SERVICE.	ULATIONS OF T	HE FEDERAL
P	PERTINE	T DETAILS OF TH	E REPAIR ARE	ON FILE AT 2816
	DetaSigned	-338	ior	
	FAA	Repair Stat February AV-AIR,INC derdale Executive		
		Lauderdale, Florida		. time .
otal To arry Forward				

Registration	No.	
--------------	-----	--

registration 140.		
and Remarks	Signature	Certificate No
AIRCRAFT PAINTING CERT	IFICATIONS	3
Aircraft Registration: N255DS Serial Number: Aircraft Model: Saratoga Date: Feb. 24.98 W.O. #: 1100 This is to certify that this aircraft was striped down of old Corrosion protection applied. Aircraft was primed with was repainted. Flight controls balanced and re-installed on the airc Carried out complete operational check on all flight controls with factory instructions for this make and model.	Make: Piper 0 1 paint. Removed co sh primer and high bu traft. Installed decal kit i. All work preformed 1 White (#1528) HT 10494 Las Vegas ver this work.	entrol surfaces. Fill primer and t. in accordance

A&P591-44-8243

AERO DESIGN, INC.

Aircraft Painting, Interiors, and Woodwork. Fort Lauderdale Executive Airport (KFXE) 5601 N.W. 15th Ave., Fort Lauderdale, FL 33309. Phone: (954) 938-2188. Fax: (954) 771-4583.

Aircraft Time		Recorder	Maintenante
This Date	Total	Reading	Molinoridate
Brought Forward			
Installed	Shader	TOTAL	zer System opsch
OK No.	Losks.	See 3	37 FORM. Respect.
ECT-1000	· with	EPM 70	1 ops ckok.
Installer	OURI	aled 1	Welsten frel Pogl
Assy	N/W 1008	of 5/1	137298 ofschol
Leste C	k ok	,	Mull
		CAV-AR IN	aFBLR8210
	F1. Lauder	sale Executive A	word 2862.
	This Date Brought Forward Tustalled Ok No ECT-100 Tustalled	This Date Total Brought Forward Tustalled Strady Ok No Loaks. ECT-1006 with Installed owner Assy My 1008 Loak Ck. Ok	This Date Total Reading Brought Forward Tustalled Shadin Total Ok No Loaks, see ? ECT-1006 with EDM 70 Installed oursepayed in Assy Mu 100806 sta

PAIRED AND INSPECTEI RENT REGULATIONS OF INSTRUMENT AND IS APP	DIN ACCORD- FTHE FEDERAL
ENGINE OR COMPONENT PAIRED AND INSPECTEIN REGULATIONS OF THE PROPERTY OF THE P	DIN ACCORD- FTHE FEDERAL
AIRED AND INSPECTEI RENT REGULATIONS O ISTEATION AND IS APP	DIN ACCORD- FTHE FEDERAL
WAS CAN WAS 12 WEL	FECAL PROPERTY OF
	•
THE REPAIR AF	REON FILE AT SA
Sea. FELM 92 (D	io
Executive Airport de, Florida	
1	
	ALS OF THE REPAIR AF THOM UNDER WORK OF THE REPAIR SO TO THE REPAIR SO TO THE REPAIR OF THE REPAIR AF THE REPAIR OF THE REPAIR AF THE REPAIR OF THE REPAIR AF

Saratoga N255DS

cabin & cockpit interior as follows:

8224006

eted aircraft through using Sandpiper Interiors Dresden 8110-3 I.D.#070296-02 dtd 7/2/96

ated & installed all cabin seating using Garrett r: Berkshire 835 Royal 8110-3 I.D.#4101 dtd 3/12/98

red & installed all side panels in cloth with leather using G.B. Steeves Theme Park Fish Pond Fabric lot Batch #H9351 8110-3 I.D.#5201 & Garrett leather: ire 835 Royal 8110-3/I.D.#4101 dtd 3/12/98

naterials meet the FAR requirements of FAR 25.853(A)

IA 22.28817 For Aircraft Interiors Coro Ft. Lauderdale, FL 33309

Curtis Yeagle Carry Forward

and Rema	rks	Signature	Certificate N
	5-8-98		
	STATIC Systom CH	vers	ļ.
*	Por Fan Pani 43 Panacraph (C)		
*provingshim	Panacraph (C)		
	CAU-Ain W/O AGO		
	Ral Fold	-821D	1
		•	

Registration No._

Date	Aircra	t Time	Recorder	Maintenance	and Remarks		Signature	Certificate No.
Date	This Date	Total	Reading	Maintenance				
6/1/98	Brought Forward							
	1-24197	Bell	red St	and By View				
		Purp ,	Asry. Al	43-1 9AM3 OPS				
		Ch o	E	CAV-AIR INC. WOX3044	•			
			FAA Approve FL Lauderda	d Repair Station #FBLR821 D le Executive Airport, Florida				
	4 8	. *		Mul		***		
	8					-		
Total To Carry Forward				1				

Registration No.		
------------------	--	--

CAV-AIR INC

CAV-AIR, INC.

5500 N.W. 21st Terrace • #9 • Fort Lauderdale, Florida 33309 FAA Approved Repair Station • FBLR 821D

Page 1 of 2 Airframe - N255DS Piper PA 32-301T Serial number 32-8224006 Tach time 2520.6 Complied with Annual/100 hour inspection using Piper forms and in accordance with FAR 43 Appendix D. Tightened loose fitting on Oxygen bottle. Replaced aircraft battery, installed new serial number G01793932, serviced tested and re installed. Removed and replaced stripped screws as necessary. Replaced two nut plates as required in left lower wing access panel. Repaired cracks in left and right wheel pans and fairings with fiberglass filler and painted as necessary. Removed left and right brake calipers, cleaned and disassembled, replaced o-rings, reassembled calipers and re installed, serviced and bled system. Ops check OK. Removed left strut installed new seals, re installed and serviced. Replaced left and right aileron bond strap. Stop drilled cracks in right rear baffle. Removed paint from stall warning and lift detector, ops check OK. Replaced left aileron rod end bearing p/n 452336 with new. Removed paint from right fuel cap. Replaced left outboard stabilator hinges p/n 63560-002. Complied with AD 93-05-22 Fuel injector I/A/W Textron Lycoming SB 342A. Complied with AD 84-26-02 Induction air filter, by replacement. Complied with AD 76-07-12 Ignition switch, by function test, OK a this time. Removed nose scissor torque links, cleaned and inspected, found bolts and bushings worn. Replaced torque link bolts and bushings with new, reassembled, lubed and installed. Ops check OK. Sprayed airframe with ACF 50. Rigged right aileron, ops check OK. Complied with AD 95-26-13 Oil cooler hoses, by inspection, found OK at this time.

	Registration No.
CAV-AIR INC	CAV-AIR, INC. 5500 N.W. 21st Terrace • #9 • Fort Lauderdale, Florida 33309 FAA Approved Repair Station • FBLR 821D
hardware in cabin door late	2 Rotary fuel pump, by checking torque, found OK at this time. Installed h as necessary. One cowl fastener missing, installed stud, grommet and snap ring. Manufacturers specifications. All systems serviced to manufacturers
pecifications. All AD's che certify that this airfram to be in airworthy conditi	ecked through 99-02F. e was inspected in accordance with an Annual/100 hour inspection and found on.
Cav-Air, Inc. FBLR 8211 Bryan Lenz	
()2/13/99 Work Order \$	33382 Tach time 2520.6

tificate No.

Total T



CAV-AIR, INC.

5500 N.W. 21st Terrace • #9 • Fort Lauderdale, Florida 33309 FAA Approved Repair Station • FBLR 821D

Airframe N255DS Piper PA 32-301 Serial number 328224006 Tach time 2063.9 Hobbs 2523.6 Removed fairings, placed aircraft on jacks, removed tire and brake assembly. Deflated strut and removed strut from spar mount. Split strut and removed top seals. Replaced top seals with new. Inspected strut for cracks. Assembled strut and filled with MIL 5606 hydraulic fluid. Installed strut on spar mount and torqued to manufacturers specs, inflated strut to manufacturers specifications in accordance with Piper Service Manual. Leak checked none noted. In stalled fairings.

F.A.A. Approved Repair Station FBLR 821D

Ft. Lauderdale Executive Airport, Florida

Cav-Air, Inc.

Bryan Lenz

02/22/00

Carry Forward

Work Order S3413

Tach time 2063.9 Hobbs 2523.6

HOB65

TACH

ration No.

ond Remarks	Signature	Certificate No
Airframe-N255DS Piper PA 32-300 Serial number 32-8224006 Tack Rotated main tires. Replaced left and right main brake linings. Reprobe. All operational checks good. F.A.A. Approved Repair Station FBLR 821D Ft. Lauderdale Executive Airport, Florida Cav Air, Inc.	h time 2554.4 aired EGT wire and replaced EGT	4 1
Bryan Lenz Date 3/24/99 Work order S3444 Hours 2554.4		1
•		

	Aircraf	† Time	Recorder	Maintenance			
Date	This Date	Total	Reading	Maintenance			
1	Brought Forward ->						
4/21/99	TACH 26	105.3		Special OX 648ply			
				Special Ox 6x 8ply			
1/18/90	TACH 7	2618.1		PLASTICS. AS per piper			
1 111				Plastics. As per piper			
		100					
Total To Carry Forward							

ond Remarks Spen Piper service on with PMA LPH926	A Publication of the Party Par	1086 Boquet Road Jeannette, PA 15644 LP# 928 Gray Applicability: Piper PA32-200 ain 32-7400001 thru 32-7800008 PA32R-300 ain 32-7440001 thru 32-7800008 pA32R-300 ain 32-7860001 thru 32-7860008 pA32R-300 ain 32-7860001 thru 32-7863002, ain 32-7863001 thru 32-7863002 pA32R-301 ain 32-808001 thru 32-786307, ain 32-808001 and up pA32-3017 PA34-200 PA-34-2001 ain 34-7870056, ain 34-8	Email: windshields@lpaero.cc OEM# 78271-06 Manufactured: APR 26 1999 940001 and up R-7885001 and up R-7987001 and up
ezula manuat			

Date	Aircraf	Time	Recorder	Maintenance			
Date	This Date	Total	Reading	Maintenanes			
	Brought Forward -						
4/24/99	TACH 26	105.3		Special Of 64 8ply			
				Special Ox 6+8ply			
4/18/99	TACH I	4618.1		Replice L& R WHOSHIELDS			
1 111				Plastics. As per piper			
Total To Corry Forward							

Registron		1
and Remarks	Celly "Fra	Alle Street
15 per piper service mount of Goodgean Fly	ht RC	
	FRANK COUR	24591745
with PMA LP#926 \$ 928 LPAGERO	Sagant Van	11R 31656 1941
reruice manual		


-			4				,
Date	Aircraf		Recorder	Maintenance	and Remarks	Signature	Certificate No.
	This Date	Total	Reading				
4/28/99	Brought +			ROMOVED TOR-950 TAANSA	NOON S/N 15783 AND INSTALLED		
				GTX 320 TRANSPONDER	1/N83201348, Janovers AR500 Best		
				ENCODER SAN 23412 AND	THE AIRTHANT ENGINE OR COMPONENT		
				S/N40940.	THE AIRPRANT PROME OR COMPONENT		
1					ABOVE MARKET WHED AND INSPECTED IN ACCORDANGE WITH CORRENT REGULATIONS OF THE FIRE PAL AVIATION AND IS APPROVED FOR		
					HETOHN TO SHAVICE.		
					PERTINENT DETAILS OF THE REPAIR ARE ON THIS FIED AIR STATION UNDER WORK ORDER NO. 14441 Date Signed Affects BLASSES PCOZSSLY		
					FAX Repair Ste. BLACTO COLSSLY CAV-AIR,INC.		
					Ft. Lauderdale Executive Airport Pt. Lauderdale, Florida		
Total To Carry Forward						<i>:</i>	

Registration No._

Date	Aircraf		AIRCRAFT LOG			4		-	The second second second second second		
Dale	This Date	Total	Recorder Reading		0	Description of the state of the		#	(- 1		
stem with fluid.	me - N255DS Piper PA 32-301T s/n 32-8224006 Tach time 2648.7 Lubed flight controls and landing gear scissors Serviced battery and brake in with fluid. Serviced main gear struts. Installed new seal on copilot door. in 50 hours. Sealed left and right brake calibers. Leak check performed, no Approved Paper Strutt.			Maintenance	ES	U.S. Depe	ORM 8 INESS APPRO	VAL TAG			recking Ref. No.
A.A. Approved P			check performed, no	_18	D. CHAPDELAN O N.W. 21 Torr It Lauderdale, I	rece 954	V422-4559 or 954/77 V493-8980 (Fax)			6. Work Or W.O. #	der, Contract, or Invoice Number
an I enz			3		ption	Part Number	0. Eligibility*	10. Quentity	11. Serial / Batch		12. Statue / Work
7/2/99 Work	Order S3541 Tach time	2648.7		D S	de zer	SSDI20	TSO	1	A409	40	C) Overhaul C) Repair Bench Check &
-						coordance with FAA regulations pecified in block 12/13 was carr insidered ready for release to se	8.				attached to this form, a that work the 1579
			7-		set be accompanie	led by maintenance history including	total / total cycles / t	lmes since ne	ow.	550 F	
rward						notified where, except its otherwise specified with FAA approval design data and describerous, guingmants of the importing country bette been seed. 16. FAA Authorization No.: 18. Date:	raturn to sa	at the work sphiness regulativice.	2	attached) above the work perfe	was carried out in accordance rmed the part(s) is (are) appre Certificate Number: WI4R623
7.00	***************************************			The second secon		W 2	22. Hanna	typed or print	00):] . (/ /	28.	Date: /22/20

	Aircraft	Time	Recorder	Maintenance
Date	This Date	Total	Reading	Mainenance
aned fuel seers. Lubed tem with flumplied with the in 50 ho ks detected. A.A. Approv. Air, Inc.	255DS Piper PA 32-301T shoreen, fuel injectors and gase flight controls and landing gaid. Serviced main gear struit AD 98-18-12 fuel pump in urs. Sealed left and right br. All operational checks OK wed Repair Station QC05363.	n 32-8224006 Ta colator. Changed ear scissors Servits. Installed new spection, fuond O ake calipers. Leaf	ch time 2648.7 vacuum inlet and relief ced battery and brake seal on copilot door. K at this time. Due	
al To				

Registration No.		
and Remarks	Signature	Certificate No
MAKIGATE MODE GAZZOS/N 83201348 91.217 were to comply wit para. "G" Nex	ondence tests required performed this date and FAR part 43 appendix certification due	found E - 2 3 - 03
THE ALTIMETER AND STATIC SYST TESTED IN ACCORDANCE WITH TH OF FAR 91.411 AND FOUND TO BE ALTIMETER TESTED TO SIGNED CAV-AIR, INC. FAA APPROVED REPAIR STATI	SATISFACTORY. FEET. FOR	



Make/Model	PA32-301m	Log Book	Reg. No. 20055DS
Serial No.	32-8224006	Entry	Date 30 March 2000
Tach/Hobbs	Repaired autopil harness by locat autopilot descon extra long interjack bracket on behind pilot sea	F.A.A. Certifled Repair Str SD4R514M ot wiring sing and remo- nect line. So lior screw ho- lower pilot at. Removed sopilot system	(954) 491-3170 Fax (954) 491-695 www.banyanalr.com ving short in hort caused by lding mike
service. Per	P or his operation has been represented by the Federal Aviatic tire. Signature	paired or tested and inspe on Agency and is approve in file at this repair station Work Order #	#SD4R514M. AIR SERVICE

and Remarks	Signature	Certificate N
Date: 06-29-2000 PAT: 2782.3 Tach: 2782.3 Installed M-20 Oil Separator System IAW STC SA2033AT, lated February 28, 2000. Installed new left main tire and tube. This Airframe is approved for return to service on W/O S4002. David M. Avery CavAir OCOR536Y		
**		-

	Aircraft	Time	Recorder		Matatanana
Date	This Date	Total	Reading	. <	Maintenance
AFTT: 2810. Complied wit Maintenance defects Com Complied wit AD 76-07-12 filter and vact 91.207 ELT c tail cone and and tightened new terminal and left brake checks, all ch I certify that Inspection an Cav-Air, Inc.	h AD 84-26-02 paper ignition switch by of uum regulator filter. Thecks good, Battery replaced nut plate. It exhaust clamps. See	a in FAR 43 A Complied with 8-12 rotary fue er induction ai perational che Serviced right replacement of Removed and rviced aircraft ubber pad on o ight main tire. I run. peen inspected to be in airwo Repair Station	ppendix D and use AD 95-26-13 oil pump torque in r filter by replace tack, checks good. It main strut. Confue March 2004, replaced corrodect battery cleaned to performed operation accordance or thy condition.	l cooler hoses, no spection, no defects. ment. Complied with Replaced central air mplied with FAR Repaired fiberglass on d hardware. Inspected erminals and installed medal. Resealed right anonal and leak	
Total To Carry Forward					1

and Remarks



Airframe - N 255
Piper PA32-301T
Tach: 2828.3
Removed vacuum
model # 211CC S/r
This airframe is apr
Cav-Air, Inc. F.A
Date: 6/20/2001 We

ı	Jnited States	2. U.S	0.1700	FAA FORM WORTHINESS A of Transportation •	8130-3 PPROVAL TAG Federal Aviation Admin	istration	3. System Tracking Ref. AA 3 5 7 5. Work Order, Contract	25
Organ	Aero Access 1240 Spring Gibsonville,	wood A	Venue				3578	25
- 1	7	8.		Number	9. Eligibility	10. Quantity	11. Serial/Balch Number	Status/Work
Hem 1	Airborne Dry Air Pu	imp		166	TBV By Installer	1	11905	Newly Overhauled
	•						on 203-6-1009	
Limited	d file parts must be accompar New Newly Overhaule hat be now or newly overhauded partial life.	ied by mair d	ntenance histor	y including total lin	ne/total cycles/time sinu 19.	08 FIGW.	bendoe in Accessions with FAR 43.9 chalf above was carried out in accommon	s with FAA Airworthinesse regulation
Limited 14. Cordina 8 manufacts 1807E In	If life parts must be accompany New Newly Overhaule that the new or ready outstanded purish into the contract of the FAA approved these comes of parts to the exponent. The special may	ied by mair d	ntenance histor cost as atturbes specialises.	ry including total tin sted in block 13 was (word) se book met.	ne/total cycles/time sinu 19.	Platum to finished: 13 (or affinited: 13 (or affinited: 13 (or affinited the partia))	bendoe in Accessions with FAR 43.9 chalf above was carried out in accommon	21. Certificate Numbe
Limited 14. Cordina 8 manufacts 1807E In	d file parts must be accompar New Newly Overhaule hat be now or newly overhauded partial life.	ied by mair d	ntenance histor cost as atturbes specialises.	y including total lin	19. Custing that the work specifies and in respect to the work specifies 20. Authorized Story	Patent to faintheat 13 (or after to faithful to faithf	benico in Accestence with FAR CLB chedi above was carled out in accordance is give approved for solute to service.	21. Certificate Numbe YV4R688M
Limited 14. Cordina 8 manufacts 107E in 15. Si	If life parts must be accompany New Newly Overhaule that the new or ready outstanded purish into the contract of the FAA approved these comes of parts to the exponent. The special may	ied by mair d	ntenance histor cost as atturbes specialises.	y including total tin alled in block 13 was (worth no been met. Authorization No.:	19. Continue that the work specifies that the work specifies that the work specifies and in respect to the work specifies and in respect to the work specifies. 20. Authorized, Sings 22. Name (Typed of	Patent to I feature to I featur	benico in Accedence with FAR CLB chedi above was carled out in accordance is give approved for solars to service.	21. Certificate Numbe YV4R688M 23. Date

Date	Aircraft Tin	10	Recorder	Maintenance	and Remarks	Signature	Certificate No.
Duie	This Date	Total	Reading	Maintenance	and kenidika	Signoisio	COMMITTED 140.
omplied with aintenance of fects. Composited with the property of the complied with the composite of the com	N 255DS Piper PA32-3 8 Tach: 2810.8 h Annual Inspection in Manual as guides. Complied with AD 98-18-12 h AD 84-26-02 paper in ignition switch by open uum regulator filter. See hecks good, Battery repreplaced nut plate. Ren exhaust clamps. Service boots. Reinstalled rubb calipers. Rotated right ecks good on ground ruthis airframe has been d was determined to b F.A.A. Approved Rep 01 Work Order S4371	FAR 43 Appropried with A rotary fuel production air fational check rviced right relacement due to rotary fuel aircraft batter pad on comain tire. Production in airwort air Station	endix D and using D 95-26-13 oil of the property of the proper	cooler hoses, no ection, no defects. ent. Complied with eplaced central air olied with FAR epaired fiberglass on ardware. Inspected ninals and installed al. Resealed right onal arti leak		n 2C057 and installed overhauled vacuum pur and operational checks, checks good on ground ru tion QC0R536Y	
I To ry Forward					Laboration		

Registration No.__

-	4
	,

Dute	Aircraft	Time	Recorder	Maintenance
Date	This Date	Total	Reading	Maintenance
	Brought +			1
/Model: PI	PER PA32301T			Reg No.:]

erial No. 328224006

ime: ACTT: 2829.7

The Aviation Professionals

Date: 06/2

Log Book Entry

REFORMED AIRCRAFT EVALUATION PER CUSTOMERS REQUEST AND PROVIDED A LIST OF DISCRAPANT DMPLIED WITH ENGINE COMPRESSION CHECK. CYLINDER DIFFERENTIAL PRESSURE AS FOLLOWS: 1) 74/80, #2) 70/80, #3) 72/80, #4) 70/80, #5) 66/80, #6) 66/80. REMOVED MUD DOBBER NEST FROM

EVATOR CABLE IN TAILCONE. END

Vork Order: 17398

Authorized Signature:

F.A.A. Certified Repair Station WD4R618M

Banyan Air Service 1635 NW 51st Place Ft. Lauderdale, FL 33309 Phone: 954.491.3170 Fax: 954.491.16

Total To	
Carry Forward	

Registration No.

and Remarks	Signature	Certificate N
Airframe - N255DS Piper PA32-301T s/n 32-8224006 Tach: 2829.8 Trouble shot CHT gauge, found broken wire. Repaired wire, operational checks good. Fabricated patch, painted and installed on pilots side interior sidewall. Replaced camlock on battery box. Installed washer on shimmy dampener bolt. Removed rust from engine mount near turbo, primed, painted and installed fire sleeve on engine mount. Serviced oxygen. All work performed in accordance with Piper Maintenance Manual. Operational checks good on ground rum. This airframe is approved for return to service. Cav-Air, Inc. F.A.A. Approved Repair Station QC0R536Y Date: 7/05/2001 Work Order: S4461 Tach: 2829.8	<i>-</i>	

D	Aircraft	Time	Recorder			Maintenance
Date	This Date	Total	Reading			Moinsenance
005 A Sycol	nicipal Airport Leesb	urg, VA 20175	YBJR768L	DATE: 08/0 MODEL: PA3 R/N: N25 S/N: 32-8 HOBBS: 242-	2-301T 5DS 224006	
1 (703) 771	-0188 FAX (703) 779-	0435		W/O: S00		-
	SI	ERVICED OXYGI	EN TO 1850 PSI.			
-	THE AIRCRAFT: ANCE IDENTIFIE ACCORDANCE VIONS AND WAS TINENT DETAIL AGENCY UNDE	AIRFHAME ENGI D ABOVE WAS RE WITH CURRENT FI APPROVED FOR S OF THE REPA	RELEASE NE-PROPELLER OF PAIRED AND INSPECTION TO SERVINAR ARE ON FILE DATE OF THE PAIRED AND THE	CTED IN REGULA- CE PER- AT THIS		
	AUTH. SIGN	ONT HAWTHORN	VE CRSYBJR 768L	77011		

	Regi	stration No.			
marks			Signature	Certificate No.	
Date: Tach:	11/10/01 2492.0		Reg. No: N255DS Ser. No: 32-8224006		
2221	Airport Highway	Horizon Avionics 7, #14, Alcoa, TN 37701. Tel: (1	s, Inc. 365) 980-7858 Fax: (865) 980-77	701	
Removed	Collins ADF system	em, Northstar Loran, King audio/m	narker panel, King #1 and #2 comm, C vacuum directional gyro. Installed G	Collins	
GNS530.	GMA340 audio p	anel. Century Flight Systems NSD	360A slaved HSI and DAP Digital Al	armin titude	
Preselect,	, #2 nav/comm Ki	ng KX155 and KI209, and PS Eng	gineering CD player. See FAA Form	337's	
this date.	. Revised equipm	ent list. Aircraft actually weigher	d by Technical Aviation Service, In	ic. on	
11/23/01. requireme	. The ICA included	d with the FAA Form 337 is now property of the page of	oart of the aircraft's inspection/mainte Flight Manual Supplements placed wi	nance	

MAINTENANCE RELEASE

The Airframe Or Appliance Identified Above Was Repaired And Inspected In Accordance With Current Maintenance Rules Of The Federal Aviation Regulations And Is Approved For Return To Service. Pertinent Details Of This Repair Are On File At This Repair Station Under Work Order No. 0079.

For Horizon Avionics, Inc. FAA CRS F3OR150X Signed.

Registration No. N2550 BIKT FILE

Date	Aircraft Time		Recorder	Malatanania	
	This Date	Total	Reading	Maintenance	
1-5-02	\			TAC-2982,00	
Replace Onspeci instille & Change	ed tue	bearings ted structured look	A B Gooly A races, le A assembly Strets to a	Pared Cylinder on soisson unit. ear flight Custom II. parked before se- with \$600 Ngd, vil. pame expension.	
				*	
otal To arry Forward					

and Remarks			ificate No.
J 18-02	100 HR. inspection this	date all NO che	though
TAC-2993.8	2002-01. all work done	I.A.W. Pipe Parts	1 Druie
Hobbs - 2344.4	maxuals, ELT ops, ale		
ITAF 2992.8	Sate 3-04. Other way	. 0	
Mist side co	ber west uplaced	. //	
	Palled Brackett air Lit		
11 . (1'	craft lubbed per, PA 3.	1	
	this aircraft has been	1	
	wers found to been a		
	ed for return to Serve		
	Unfor St. A+P30350		