THE PROPERTY OF LOO DOON #/ Van Nuys Flight Center, Inc. Van Nuvs, CA N8403D WO 5431 14-SEP-07 Tach 729.0 Complied with Annual Inspection per Piper service manual. I certify this propeller has been inspected in accordance with the manufacturer's inspection and determined to be in airworthy condition. The aircraft and/or component identified above was repaired and inspected in accordance with current federal air regulations and is approved for return to service only for the work accomplished. Pertingnt details of the repair are on file. AP549927542IA SIGNATURE Chris Wood Certificate Number Van Nuys Flight Center, Inc. Van Nuys, CA N8403D WO 6035 21-Oct-08 Tach 871.6 Complied with Annual Inspection per Piper Service Manual. I certify this propeller has been inspected in accordance with the manufacturer's inspection and determined to be in airworthy condition. The aircraft and/or component identified above was repaired and inspected in accordance with current federal air regulations and is approved for return to service only for the work accomplished. Pertinent details of the repair are on file. William P. Noctor AP2192808IA Certificate Number

The Santa Wall Suna

Van Nuys Flight Center, Inc. Van Nuys, CA

N8403D WO 6655 1-Dec-09 Tach 1052.8 Hobbs 849.7 Complied with Annual Inspection per Piper Service Manual.

I certify this propeller has been inspected in accordance with the manufacturer's Annual inspection and determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current federal air regulations and is approved for return to service only for the work accomplished. Pertinent details of the repair are on file.

William P. Noctor	Most	AP2192808IA Certificate Number	47	
				_ 1 a 7
			1900	

SIGNATURE

Date: 11/

Inspected spinner b

I certify to

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES. SERVICE BULLETINS, SERVICE LETTERS & MINOR ADJUSTMENTS

DATE	TACH TIME DESCRIPTION OF WORK		SIGNATURE	
		SEE AIRFRAME LOGBOOK		
-		K2 840 3D		
Date: 11/4/2017	N8403D Tach: 1356.4	Prop Log Entry Hartzell HC-E3YR-1RF s/n FM70 TT: unkn TSPOH: 678.2	33	
Inspected IAW FA spinner bulkhead.	R43 appendix D cl	necklist. Serviced prop with Aeroshell 6 grease. Replaced	d anti chafe tape on forward	
I certify that this P in airworthy condition	ROPELLER has be	een inspected in accordance with an ANNUAL inspection	n and was determined to be	
ATTITUDE AVIAT	TION, Inc., 299 W. J	Eric Niedrauer A&P 2783808 IA ack London Blvd, Livermore, CA 94551 Ph. 925-456-2276 En	nail: info@attitudeaviation.com	

SERVING THE GOLD CUM

SIGNATURE

* Riviera Beach, Florida 33404 * Phone (305) acc

Phone (305) 800

off 1

835 W 13th Court

	N8403D Date: 11/16/2018 Tach: 1515.7	Prop Log Entry Hartzell HC-E TT: unkn TSPOH; 837.5	E3YR-1RF s/n FM703					
	Inspected IAW FAR43 appendix D checklist. Serviced prop with Aeroshell 6 grease. Dressed blades, cleaned and painted rear faces.							
	I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in air vorthy condition. Eric Niedrauer A&P 2783808 IA ATTITUDE AVIATION, Inc., 299 W. Jack London Blvd, Livermore, CA 94551 Ph. 925-456-2276 Email: info@attitudeaviation.com							
V								
			Za					