

The Standard

PROPELLER LOG

ASA S.P.L.

The Standard Propeller Log
SP-L

© 1994 Aviation Supplies & Academics, Inc.

ASA-SP-L

ISBN 978-1-56027-418-6

All rights reserved.
Reproduction or use, without written permission,
in any manner, is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE
Newcastle, WA 98059-3153
Website: www.asa2fly.com
Email: asa@asa2fly.com

Printed in the United States of America

19/2019

TRANSPORTATION USD \$4.95

ISBN 978-1-56027-418-6



Propeller Record General Information

Propeller Manufacturer McCaughey

Model 2A34C 203

Hub Series # 756443

Date of Manufacture _____

Type _____

Blade # _____

Aircraft Installed On: **Make/Model**

Cessna 182P N1575\$

Serial # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____

Date: _____

Next Inspe
Due: _____

MICHIANA AIRCRAFT SERVICE, INC.
4323 West Progress Drive South Bend, IN 46628

Prop Log Entry

Phone: 574-287-4687 Fax: 574-287-7753

Cessna 182P
TTA: 5620.6

N1575S
SPOH: 1784.6

Inspections (complied with the following)

- Complied with an Annual inspection.

Year: _____

Date: _____

Next Inspe
Due: _____

This Aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed.

I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be airworthy at this time. All AD's checked up to revision dated 4-20-11.

Year: _____

Date: _____

Next Inspe
Due: _____

Signature:  John C. Hoffa
Michiana Aircraft Services, Inc. C.R.S. Q6MR956Y
Date: 4-20-11 Work Order #8063

Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 182P

N1575S

TAT5632.5 SPOH: 1796.5

Inspections:

- Complied with Annual inspection.

Maintenance:

- Dressed prop.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current till 4-24-12.

Signature:  John C Hoffa
Michiana Aircraft Service, Inc. C.R.S. Q6MR956Y

Date: 4-24-12

Work Order #8802

Year: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
Overh

Year: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
Overh

Year: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
Overh

HUB & BLADE INSPECTIONS. REPAIRS AND ALTERATIONS

Year: _____	Total Tim in Service
Date: _____	
Next Inspection Due:	Time Sinc Overhaul

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesnna 182P N1575S
TAT: 5643.6 SPOH: 1807.6

Inspections:

- Complied with Annual inspection.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current till 4-22-13.

Signature:  John C Hoffa C.R.S. Q6MR956Y
Date: 4-22-13 Work Order #9564

Year: _____	Total Tim in Service
Date: _____	
Next Inspection Due:	Time Sinc Overhaul

Year: _____	Total Tim in Service
Date: _____	
Next Inspection Due:	Time Sinc Overhaul

TERATIONS

Year: _____	Total in Ser
Date: _____	
Next Inspection Due:	Time Overh

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesnna 182P N1575S
TAT: 5655.8 SPOH: 1819.8

Inspections:


- Complied with Annual inspection.

Maintenance:

- Dressed prop.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current till 4-29-14.

Signature:  John C Hoffa C.R.S. Q6MR956Y
Date: 4-29-14 Work Order #10369

Year: _____	Total in Ser
Date: _____	
Next Inspection Due:	Time Overh

Year: _____	Total in Ser
Date: _____	
Next Inspection Due:	Time Overh

HUB & BLADE INYear: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
OverhYear: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
OverhYear: _____ Total
in Ser

Date: _____

Next Inspection
Due: _____ Time
Overh

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 182P N1575S

TAT: 5666.3 SPOH: 1830.3

Inspections:

- Complied with Annual inspection.

Maintenance:

- Dressed prop.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 5-8-15.

Signature:  John C Hoffa C.R.S. Q6MR956Y

Date: 5-8-15 Work Order #11088

Year: _____ T
ir

Date: _____

Next Inspection
Due: _____ T
OYear: _____ T
ir

Date: _____

Next Inspection
Due: _____ T
OYear: _____ T
ir

Date: _____

Next Inspection
Due: _____ T
O

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 182P N1575S

TAT: 5679.3 SPOH: 1843.3

Inspections:

- Complied with Annual inspection.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 3-29-16.

Signature:  John C Hoffa C.R.S. Q6MR956Y

Date: 3-29-16 Work Order #11601

ALTERATIONS

Year: _____	Total Tin in Servic
Date: _____	
Next Inspection Due:	Time Sir Overhau

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 182P N1575S

TAT: 5698.6 SPOH: 1862.6

Inspections:

- Complied with Annual inspection.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 4-21-17.

Signature:  John C Hoffa C.R.S. Q6MR956Y
 Date: 4-21-17 Work Order #12161

Year: _____	Total Tin in Servic
Date: _____	
Next Inspection Due:	Time Sin Overhau

Year: _____	Total Tin in Servic
Date: _____	
Next Inspection Due:	Time Sin Overhaul

Year: _____	
Date: _____	
Next Inspection Due:	

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 182P N1575S

TAT: 5702.9 SPOH: 1866.9

Inspections: 23w

- Complied with Annual inspection.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 5-14-18.

Signature:  Michael Hannon C.R.S. Q6MR956Y
 Date: 5-14-18 Work Order #13035

Year: _____	
Date: _____	
Next Inspection Due:	

Year: _____	
Date: _____	
Next Inspection Due:	

AIRWORTHINE!

Year: _____ Tot: _____
Date: _____
A.D. # _____

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cessna 182P N1575S


TAT: 5713.0 SPOH: 1877

Inspections: 23w

- Complied with Annual inspection.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 5-10-19.

Signature:  Steve Purvis C.R.S. Q6MR956Y

Date: 5-10-19 Work Order #13963

Next Inspection Due: _____

Mech

Year: _____ Tot: _____
Date: _____

A.D. # _____

Next Inspection Due: _____

Mech

DIRECTIVES

Year: _____ Total _____
Date: _____
A.D. # _____

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cessna 182P N1575S

TAT: 5718.1 SPOH: 1882.1

Inspections:

- Complied with Annual inspection.

Mech. Maintenance:

- Dressed prop.

Next Inspection Due: _____

Year: _____ Total _____
Date: _____

A.D. # _____

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined airworthy at this time. All AD's current through 5-6-2020.

Signature:  Steve Purvis C.R.S. Q6MR956Y

Date: 5-6-2020 Work Order #14826

Next Inspection Due: _____

Mech.