

The Standard PROPELLER LOG

ASA-SP-L

Propeller I	NO	RTHERN AIR	
Model	Prop LOG BOOK ENTRY	Dated: 04/09/03	N 0000D
Hub Series	Make: Hartzell	Model: HC-I3YR-1RF	N 989SR SN: HK784B
	Total Time: 45.6	Hobbs Time: 45.6	014. 1110 040
Date of Ma			
	I certify that th	done per the Piper PA-32R maintenance mains aircraft has been inspected in accordance with a in an airworthy condition. Pertinent details on file Signed:	an Annual

ext Inspection ue:	Time Since Overhaul						
oar:	Total Time in Service	Description					
		Mech. Cert. # or Repa	air Station #				
noted	d. This work was tify that this airc Order # 41688	done per the Piper PA- craft has been inspected in an airworthy condit Signed:	al and leak check, as needed, on the above listed items, and no discrepancies were ne per the Piper PA-32R-301T series maintenance manual. It has been inspected in accordance with an Annual Inspection and was determined to an airworthy condition. Pertinent details on file at this agency under; Signed: FOR N81R812N P.O. Box 888380, Gerald R, Ford Int'l Airport, Grand Rapids, MI. 49588-8380				
Perfo	rmed a 100 Hou	r/Annual inspection on	this propeller per	the manufacturers ma	intenance manual.		
lext lı P	Propeller log book entry Date: 10/27/2004 10/27/2004 Total Time: Make: Hartzell Model: HC-13YR-1RF Serial No: HK784B						
ear: . late:		NORT	NORTHERN		N 989SR		

		HUB &	BLADE INSPECTIO	NS, REPAIRS AND ALTERA	TIONS
Year:					
Date:	14	ORTHERN	AIR	N 989SR	
Next Inspection	Propeller log book entry Make: <u>Hartzell</u>	Date: <u>10/19/2005</u> Model: <u>HC-I3YR-1RF</u>	Serial No: <u>HK784B</u>	Hobbs: 143.5 Prop Total Time: 143.5	
	Performed a 100 Hour/Annual Profiled prop blades and appli	Inspection on this propeller pe led epoxy black prop point to	er the manufacturers main aft facing side of blades.	ntenance manuol.	
Year:	Performed an operational and noted. This work was done per	d leak check, as needed, on the	ne above listed items, and	d no discrepancies were	-
Date:	The work identified above was	performed in accordance wi	th the current Federal Avi	ation Regulations and was	
Next Inspecti Due:	I certify that this aircraft has be in an airworthy condition. Pert Work Order # 43619	n to service. Pertinent details een Inspected in accordance	are on file at this agency with an Annual Inspection oncy under;	under; n and was determined to be	
Year:	III SOLAIPA				
Date:					
Next Inspection Due:	Time Since Overhaul				

Mech. Cert. # or Repair Station #_

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-I3YR-IRF

PROPELLER S/N _ HK 784B

LOGBOOK #__/

Northern Air P.O. 80x \$88380, Gero Prop log book Make: Performed a 100 hot Performed an oper work was done per	Propeller lag book entry Make: Harizell Model: HGJ3YR-IRF Serial No: HK7848 Prop Total Time: 175,8 Proprofest From T
P.O. 80x 868380, Gero Prop log boo Make: Performed a 100 ha Performed an open work was done per	
P.O. 80x 868380, Gero Prop log boo Make: Performed a 100 ha Performed an open work was done per	
this aircraft has bee	ald R, Ford Int'l Airport, Grand Rapids, Mt. 49588-8380 N989SR
PA32R-301/301T (SARA)	A6385 Signed: Wayne Bishop; Archaff, INC. HIGH PERFORMANCE AIRCRAFT, INC. Repair Station No. HPRR569X 1830 JOB CROSSON DRIVE El Cajon, CA 92020 Phone: 858-578-5000 ALL INSPECTION IN ACCORDANCE WITH FAR PART 43, APPENDIX D, USING CURRENT LTOGA II HP/TC) MAINTENANCE MANUAL 5-20-00 CHECKLIST AS A GUIDE. ALL AD'S CHECKED E ATTACHED LIST DRESSED PROP BLADES
	nt(s) indentified above was repaired and inspected in accordance with current maintenance rules of the Federal Aviation I for return to service. Pertinent details of this repair are on file at this repair station under Work Order No. 4457-04-2008

Page 1

Propeller	Hre Service Documents. Overhaul, Major or Minor Repair, and Inspections.
TSN TSO	Propeller HC-I3YR-1RF S/N HK784B Date 4/1/2009 TTSN 447.8 TACH N/A TSMOH HOBBS 447.8 TSPOH N/A Filed and painted propeller. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.
	SIGNED Kevin Booth A&P 2764111 I.A.
	Propeller HC-I3YR-1BF S/N HK784B Date 5/5/2010 TTSN 558.1 TACH N/A TSMOH HOBBS 558.1 TSPOH N/A I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.
	SIGNED France Company
	Kevin Booth A&P 2764111 I.A.
	Propeller HC-I3YR-1RF S/N HK784B Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED SIGNED
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED SIGNED
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED SIGNED
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED SIGNED
	Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED A A STATE OF THE STATE O

	SIGNED Kevin Booth A&P 2764111 I.A.	
)		
OF 17	Propeller HC-I3YR-1RF S/N HK784B Date 6/6/2011 TTSN 669.0 TACH N/A TSMOH HOBBS 669.0 TSPOH N/A Filed nicks from leading edge of blades and painted backside of blades. I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition. SIGNED Kevin Booth A&P 2764111 I.A. NorthStar Aircraft Maintenance 5600 N Hwy 95, Bidg H100 Lake Havasu City, AZ 86404 Pht(928) 764-1999	
Date: 5/30/20 Shop Order #: Completed 10	012; Aircraft: N989SR; Type: PA32R-301T; S/N: 3257268; Hobbs: 732.30; Total Time:; Engine - Tet HII-12-0741, Closed: 4/19/2012 Dohr/Annual inspection per FAR 43, Appendix D.and current PA32R-301/301T MM. his Propeller was inspected I.A.W. an Annual Inspection and was determined to be in an Airworth LA1812608 Steven A. Wilbur	

	Prop TSN	eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	-
6/13/13	984,3		984.3	COMPLIED WITH AN ANNUAL INSPECTION DRESSED F	7ROP.
				BLADES, LUBED AND INSPECTED PROP. HUBS. CHECKED A	AD
				COMPLIANCE THRU 2013-11	
				contry that this PROPELLER has been appointed as recordance with AN ANNUAL	en
				The state of the s	in
				ALBERT A. ANCOLUAN AS SETIMA	- Maria
	Page Fie 207 Dan	ld Airpo ley Drive ers, Flori	rt (FMY) e da 33907	No.	
	Da	te	Hour mete	er Total time	
	07/09/ Dressed		1167.9 Lubed wit	ith Aeroshell 6. I have inspected this propeller in accordance with an annual inspection and	
	I certify th	nat the ab	rworthy concoverstated administration	maintenance and/or inspection was performed in accordance with the current regulations of the on and the aircraft identified above is presently approved for return to service. John A Richardson 262536133 IA	
				PROP MODEL: Bartelt Aviation, Inc. DATE: 4/9/2015 HC-I3YR-1RF PROP SN: HK784B 1301 West Lafayette Street DATE: 4/9/2015 A/C TSN: 1183 PROP TT: 1183 TSPOH: 1183	
				REG. NO: N989SR Sturgis, MI 49091 HOBBS: 1183 WORK ORDER: Phone: 269-651-5431	
	-			REG. NO: N989SR Sturgis, MI 49091 HOBBS: 1183 WORK ORDER: Phone: 269-851-5431 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop.	
				WORK ORDER: BA-00252-03-2015 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop	
				WORK ORDER: BA-00252-03-2015 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order	
				Work ORDER: BA-00252-03-2015 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order No. BA-00252-03-2015, Dated 4/9/2015 DATE: 4/9/2015 SIGNED: Work Order: BA-00252-03-2015 Work Order: BA-00252-03-2015	
				Work ORDER: BA-00252-03-2015 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order No. BA-00252-03-2015, Dated 4/9/2015 DATE: 4/9/2015 SIGNED: Work Order: BA-00252-03-2015 Work Order: BA-00252-03-2015	
				Work ORDER: BA-00252-03-2015 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order No. BA-00252-03-2015, Dated 4/9/2015 DATE: 4/9/2015 SIGNED: Work Order: BA-00252-03-2015 Work Order: BA-00252-03-2015	
				WORK ORDER: Phone: 269-851-5431 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order No. BA-00252-03-2015, Dated 4/9/2015. DATE: 4/9/2015 SIGNED: Work Order: BA-00252-03-2015 Kerry Allan Hyde, IA: 3134493 Printed by EBis 3 (datcomedia.com)	
				WORK ORDER: Phone: 269-851-5431 Prop Entries Dressed prop and spot painted back of blades Safetied prop attach nuts with 0.041 wire Adjusted prop governor stop. Maintenance Release The aircraft and/or component(s) on N989SR was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file under Work Order No. BA-00252-03-2015, Dated 4/9/2015. DATE: 4/9/2015 SIGNED: Work Order: BA-00252-03-2015 Kerry Allan Hyde, IA: 3134493 Printed by EBis 3 (datcomedia.com)	

			1						
Date	TSN	eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspection	ıs.				
8/1/2015	1234.9		1234.5	PERSORMES PULLER INSPECTION. DREISES PROPELER					
				INSPECTO MO LUBRICATED MUB. CHECKED AD	,				
				COMPLIANCE THROUGH 8/1/2015. I CERTIZY TUA-	7 7415				
				PROPELLER HAS BEEN LUSPECTES IAW AN MINUTE IA	usteriou				
				- WAS DETERMINED TO BE IN MY AIRWORTHY ROUS,	2,0N A7				
				TUIS TIME DIE DE STRESTO					
				Noncon					
		DAT	ΓE: 9/9/	/2016 HOBBS: 1377.6 N989SR -					
		I C	ERTIF	Y THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE					
				ANNUAL INSPECTION AND WAS DETERMINED TO BE IN HY CONDITION					
		_ '		JOHN PRUSSMAN -					
		_		2784903 WP VA					
				V					
-				PROP MODEL:	B B				
	-			Prop Entries Performed Annual/100hr Inspection on Propeller per guidelines of the PA-32R-301T Inspection Report and MM. C/W 100hr Propeller Hub Lubrication. Inspected Spinner and Mounting Hardware for defects. None noted.					
				I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.					
				DATE: 10/2/2017 SIGNED: Work Order: BA-00462-08-2017					
				Larry E. Russell, IA: 3531609 Printed by EBis 3 (datcomedia.com)	,				
7,									
				1 of 1					

Date					1						
					NAVE	ES AV	IATION				
				9	464 Co. R	d. 14 Wau	seon, Oh 43567				
						419-335-3	3993				
	Date: 11	1/15/2018	Model P	A-32R-301T	Hobl	bs 1617.3	Total time 1617.3				
	- N989SR		S/N 3257	7268	TSMO	OH 1617.3	Engine TIO-540-A	H1A	Serial L-1108	2-61A	
		er Model H			I HK784B		Г 1617.3			la deservant	
	and rein	ned annual istalled spi rworthy co	nner asse	n IAW PA-32-3 mbly. I certify t	01T and Har this propelle	rtzell manual er has been ir	. C/W 100 hr lubrica nspected IAW an an	ition Dress nual inspe	ed propeller b ction and was	determined to	ed
	Richard	Lee Naves	IA 34621	272 58							
								. 1			
		U									
						•					
	T			1							
-	-	-									
-		1					,				
					-						